



ALUMINIUM SURFACES

Surface should be free from dust, dirt and grease. This surface is not one that normally corrodes however, in Industrial environments, pitting and surface corrossions may develop.

- System 1: One coat Sissons One Pack Etch Primer
 One coat Sissons Zinc Chromate Primer Red or Yellow
- System 2: One coat Sissons One Pack Etch Primer
 Two coats Sissons Super Gloss Paint
 (Sissons Marine Gloss or Sissons Industrial Enamel could also be used)
- System 3: One coat Sissons One Pack Etch Primer
 One coat Sissons Zinc Chromate Primer
 One or two coats Weatherguard Emulsion

GALVANISED METAL – WEATHERED

Galvanized surface weathered for more than six (6) months are to be washed to remove accumulated dirt and finished as follows:

Priming: One coat Sissons Zinc Chromate Primer Red or Yellow or
 One coat Sissons Zinc Phosphate Primer White
 One or two coats Sissons Super Gloss or Sissons Roofcote.

NEW GALVANIZED SURFACES

Priming: One Coat Sissons One Pack Etch Primer

1. One coat Sissons Zinc Chromate Primer Red or Yellow or
2. One coat Sissons Zinc Phosphate Primer White

Finishing:

1. One or two coats Sissons Gloss or Sissons Roofcote or
2. One or two coats Sissons Weatherguard Exterior Emulsion Paint.

These recommendation and data are offered in good faith, but without guarantee or warranty, as conditions and methods of use of our products are beyond our control

ANSA Coatings Limited